



A HEICO COMPANY

SERVICE BULLETIN: SB-DK120/90-2015-001

SERVICE BULLETIN

FOR

UNDERWATER LOCATING BEACON

DUKANE SEACOM INC. PART NO.

DK120/90

PREPARED BY:

DUKANE SEACOM INC

REVISION: B

ENG APPROVED:

DATE:

2/23/17

QA APPROVED:

DATE:

2/23/17

UNCONTROLLED WHEN PRINTED

<h1>Service Bulletin</h1>	<p>Doc No: SB-DK120/90-2015-001 Rev B Date: 22 Feb 17</p>
	<p>SUBJECT: Interchangeability of New 90 Day DK120/90 Underwater Locating Beacon</p>

I. PLANNING INFORMATION

A. EFFECTIVITY

This service bulletin applies to the following part numbers:

<u>Dukane Seacom P/N:</u>	<u>SERIAL NUMBERS:</u>
DK100	ALL
DK100/90	ALL
DK120	ALL
DK120/90	ALL

B. REASON

Dukane Seacom Inc has recently received TSO-C121b approval for their 90 Day DK120/90 Underwater Locating Device (ULD). These ULD's are immediately available for sale and installation.

The FAA has withdrawn all TSO-C121 and TSO-C121a approvals for future manufacture of 30 Day ULB's beyond 01 March 2015. This affects future shipments of DK100, DK100/90, and DK120 ULD's. Only TSO-C121b approved ULD's will be authorized for manufacture after this date.

The DK120/90 is "one-way" interchangeable with the DK100, DK100/90, and DK120 and can directly replace these devices without any required modification.

This service bulletin does not supersede aircraft manufacturers' approved airworthiness configuration.

C. REFERENCES – Technical Standard Order (TSO):

1. TSO-C121
2. TSO-C121a
3. TSO-C121b