



Dated: February 18th, 2026

Dukane Seacom acknowledges the issuance of Transport Canada Airworthiness Directive CF-2026-05, effective February 13, 2026. This AD addresses degraded 121.5 MHz homing beacon performance in RESCU 406AFN2 (P/N 51090152-2, 51090414-1, 51090130-2) and RESCU 406SG (P/N 51090368-1).

Dukane has worked with Honeywell and the TCCA closely on this directive and to provide support. Dukane Seacom has engaged with Turner Aviation to implement the Service Bulletins identified in the AD and will provide full support for compliance with the 36-month mandate.

The serial numbers of the affected ELT units are identified in the applicable Honeywell Service Bulletins referenced in AD CF-2026-05, Table 1. Operators should contact Turner Aviation, report@turner-aviation.co.uk, directly to schedule accomplishment of these Service Bulletins.

A handwritten signature in blue ink, appearing to read "Sean Tancey".

Sean Tancey
Vice President/General Manager – Dukane Seacom